

Pledge Products

Cannisters may explode if neat heat. Do not puncture cannisters.



First aid measures:

Eye Contact	Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for any remove any contact lens. Continue to rinse for at least 15 minutes. Keep eyes wide open while rinsing. Do not rub affected area. Get medical attention if irritation occurs.
Inhalation	No special requirements. Remove to open air.
Skin Contact	Wash off immediately with plenty of water while removing contaminated clothing.
Ingestion	Wash out mouth thoroughly with water. Do not induce vomiting.

Handling and storage:

Keep tightly closed.
Store in a well-ventilated place. Keep cool.
Protect from sunlight.
Store in a well-ventilated place.

Keep away from sources of ignition - No smoking.
Take measures to prevent the build up of electrostatic charge.
Use only non-sparking tools.
Use explosion-proof equipment.
Ground/bond container and receiving equipment.